BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY	
UNIQUE SITE NO. 019-40-003 QUAD 621 446 / 49 66 436	O N. R.
SERIES 34 ACDES	-

1979


UNIV. P.

YOUR NAME	C.D. DeRoche/Russ Bordeau DATE: 9/78	
YOUR ADDR	ESS: C.C.H.A., Plattsburgh, NY TELEPHONE: 518-561-0340	JAN 0 9
ORGANIZATI	ON (if any)H.A.D.A.C., P.O. Box 274, Hurley, New York	
* * * * * * * * * IDENTIFICATION	* * * * * * * * * * * * * * * * * * *	
1. BUILDING NAM	FISH S.F. VITAS Home FOR AGED & INFIRMED LADIES	
2. COUNTY:	Clinton TOWNCITY Plattsburgh VILLAGE:	
3. STREET LOCAT	E(S): S.F. Vilas Home For AGED & INFIRMED LADIES Clinton TOWNCITY Plattsburgh VILLAGE: TON: Northwest Corner of Beekman and Cornelia Streets	
4. OWNERSHIP:	a. public 🗆 b. private 🗵	
5. PRESENT OWNE	a. public D b. private 🗵 R: S.F. Vilas Home ADDRESS: Beekman and Cornelia St residence for aged ladies Present: same	reets
6. USE: Original: _	residence for aged ladies Present: same	
7. ACCESSIBILITY	TO PUBLIC: Exterior visible from public road: Yes 🖾 No 🗆 Interior accessible: ExplainNo	
DESCRIPTION	TO THE RESIDENCE OF THE PARTY O	
8. BUILDING MATERIAL:	a. clapboard b. stone c. brick d. board and batten e. cobblestone f. shingles g. stucco other:	
9. STRUCTURAL SYSTEM:	a. wood frame with interlocking joints b. wood frame with light members	
(if known)	c. masonry load bearing walls 🗓	
	d. metal (explain)	
	e. other	
0. CONDITION:	a. excellent 🖾 b. good 🗆 c. fair 🗆 d. deteriorated 🗆	
1. INTEGRITY:	a. original site 🖾 b. moved 🗌 if so, when?	
	c. list major alterations and dates (if known):	

I storey shed-roof clapboard addition at rear.


13. MAP:






	14.	THREATS TO BUILDING: a. none known \(\bar{\text{N}} \) b. zoning \(\bar{\text{C}} \) c. roads \(\bar{\text{C}} \) d. developers \(\bar{\text{C}} \) e. deterioration \(\bar{\text{C}} \)
		f. other:
	15.	RELATED OUTBUILDINGS AND PROPERTY: a. barn b. carriage house c. garage d. privy e. shed f. greenhouse g. shop h. gardens i. landscape features: j. other:
	16.	SURROUNDINGS OF THE BUILDING (check more than one if necessary): a. open land b. woodland c. scattered buildings d. densely built-up e. commercial f. industrial g. residential the school/hospital
•	17.	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district)
		East (facade): residences opposite; North: residences opposite; West: parking lot, residences, offices; South: State University and parking lot. parking lot, residences, offices; South: State University and parking lot. THE HOMINATED PROJECTY IS THE HISTORY PARKED TAX MAP. BOWN ATTES DELIKERED ON THE ATTACHED TAX MAP.
	18.	STUDE NOWARLE FRATURES OF BUILDING AND SITE (including interior features, if kilpwil).
	<u>SIG</u> 19.	NIFICANCE DATE OF INITIAL CONSTRUCTION: 1889 on cornerstone (southside)
		ARCHITECT: MARCUS F. FRESERIC CUMMINGS
		BUILDER: Harriet Hunt Vilas
	20.	HISTORICAL AND ARCHITECTURAL IMPORTANCE: The S.F. Vilas Home for Aged and Infirmed Ladies was erected and endowed by Mrs. Vilas in memory of her husband, Samuel F. Vilas. It was dedicated on March 3, 1890 and was "well adapted to promote the comfort and convenience of its occupants." There are three floors with accommodations for 44 people who must be residents of Clinton, Essex or Franklin counties. This building is one of the earliest institutional structures in the city and a fine imposing example of Queen Anne architecture in the locale.
	21.	SOURCES: Plattsburgh Daily Press - Souvenir Industrial Edition (1897), p. 34.
	22.	THEME: Late 19th century institutional architecture.

- All Control of the Control of the



PLATTSBURGH CITY MULTIPLE RESOURCE AREA S.F. VILAS HOME FOR AGED & INFIRMED LADIES N.W. CORNER BEEKMAN AND CORNELIA STS. CLINTON COUNTY PLATTSBURGH, NY



SOUTH TAGADE, LOOKING NORTH